

Location:	Bruchez #1
Line:	Well to Treater
Technicians:	Matthew Ingve
Date:	8/30/2018
Time	Pressure (PSI)
10:51:00 AM	1.7
10:51:30 AM	1.7
10:52:00 AM	1.7
10:52:30 AM	1.6
10:53:00 AM	1.6
10:53:30 AM	2
10:54:00 AM	20.9
10:54:30 AM	44.6
10:55:00 AM	44.2
10:55:30 AM	44.1
10:56:00 AM	44.1
10:56:30 AM	44
10:57:00 AM	43.9
10:57:30 AM	43.9
10:58:00 AM	43.9
10:58:30 AM	43.9
10:59:00 AM	43.9
10:59:30 AM	43.8
11:00:00 AM	43.8
11:00:30 AM	43.8
11:01:00 AM	43.8
11:01:30 AM	43.8
11:02:00 AM	43.8
11:02:30 AM	43.8
11:03:00 AM	43.8
11:03:30 AM	43.8
11:04:00 AM	43.7
11:04:30 AM	43.7
11:05:00 AM	43.7
11:05:30 AM	43.7
11:06:00 AM	43.7
11:06:30 AM	43.7
11:07:00 AM	43.7
11:07:30 AM	43.7
11:08:00 AM	43.7
11:08:30 AM	43.6
11:09:00 AM	43.6
11:09:30 AM	43.6
11:10:00 AM	43.6
11:10:30 AM	43.6
11:11:00 AM	43.6
11:11:30 AM	43.6

11:12:00 AM	43.6
11:12:30 AM	43.6
11:13:00 AM	43.6
11:13:30 AM	43.6
11:14:00 AM	43.6
11:14:30 AM	43.6
11:15:00 AM	43.6
11:15:30 AM	43.6
11:16:00 AM	43.6
11:16:30 AM	43.6
11:17:00 AM	43.6
11:17:30 AM	43.6
11:18:00 AM	43.6
11:18:30 AM	43.6
11:19:00 AM	43.6
11:19:30 AM	43.6
11:20:00 AM	43.6
11:20:30 AM	43.6
11:21:00 AM	43.6
11:21:30 AM	43.6
11:22:00 AM	43.6
11:22:30 AM	43.6
11:23:00 AM	43.6
11:23:30 AM	43.6
11:24:00 AM	43.6
11:24:30 AM	43.6
11:25:00 AM	43.6
11:25:30 AM	43.6
11:26:00 AM	43.6
11:26:30 AM	43.6
11:27:00 AM	43.6
11:27:30 AM	43.6
11:28:00 AM	43.6
11:28:30 AM	43.6
11:29:00 AM	22.1
11:29:30 AM	2.3
11:30:00 AM	2.3
11:30:30 AM	2.1
11:31:00 AM	2.1
11:31:30 AM	2.1
11:32:00 AM	2.1

% loss over 30 minutes	1.13%	Less than 10%	Yes
% loss in last 5 minutes	0.00%	Less than 1%	Yes

Pass/Fail

Pass

