

Location:	Bruchez C#1
Line:	Well to Treater
Technicians:	Bill Espinosa
Date:	10/24/2019
Time	Pressure (PSI)
11:44:40 AM	0.8
11:45:10 AM	0.9
11:45:40 AM	0.4
11:46:10 AM	0.7
11:46:40 AM	0.9
11:47:10 AM	50.7
11:47:40 AM	50.7
11:48:10 AM	50.7
11:48:40 AM	50.7
11:49:10 AM	50.6
11:49:40 AM	50.5
11:50:10 AM	50.5
11:50:40 AM	50.4
11:51:10 AM	50.4
11:51:40 AM	50.4
11:52:10 AM	50.4
11:52:40 AM	50.4
11:53:10 AM	50.4
11:53:40 AM	50.4
11:54:10 AM	50.4
11:54:40 AM	50.3
11:55:10 AM	50.3
11:55:40 AM	50.2
11:56:10 AM	50.2
11:56:40 AM	50.1
11:57:10 AM	50.1
11:57:40 AM	50
11:58:10 AM	50
11:58:40 AM	50
11:59:10 AM	50
11:59:40 AM	50
12:00:10 PM	50
12:00:40 PM	50
12:01:10 PM	49.9
12:01:40 PM	49.9
12:02:10 PM	49.9
12:02:40 PM	49.9
12:03:10 PM	49.8
12:03:40 PM	49.8
12:04:10 PM	49.8
12:04:40 PM	49.8
12:05:10 PM	49.8

12:05:40 PM	49.7
12:06:10 PM	49.7
12:06:40 PM	49.7
12:07:10 PM	49.7
12:07:40 PM	49.7
12:08:10 PM	49.7
12:08:40 PM	49.7
12:09:10 PM	49.6
12:09:40 PM	49.6
12:10:10 PM	49.6
12:10:40 PM	49.5
12:11:10 PM	49.5
12:11:40 PM	49.5
12:12:10 PM	49.5
12:12:40 PM	49.5
12:13:10 PM	49.5
12:13:40 PM	49.4
12:14:10 PM	49.4
12:14:40 PM	49.4
12:15:10 PM	49.4
12:15:40 PM	49.4
12:16:10 PM	49.4
12:16:40 PM	49.4
12:17:10 PM	49.4
12:17:40 PM	49.4
12:18:10 PM	49.3
12:18:40 PM	49.3
12:19:10 PM	49.3
12:19:40 PM	49.3
12:20:10 PM	49.3
12:20:40 PM	49.3
12:21:10 PM	49.3
12:21:40 PM	49.2
12:22:10 PM	49.2
12:22:40 PM	49.2
12:23:10 PM	48.4
12:23:40 PM	48.3
12:24:10 PM	0.9
12:24:40 PM	1
12:25:10 PM	1
12:25:40 PM	0.7
12:26:10 PM	0.9
12:26:40 PM	0.8

% loss over 30 minutes	2.96%	Less than 10%	Yes
% loss in last 5 minutes	0.40%	Less than 1%	Yes

Pass/Fail

Pass

