

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402354494

Date Received:  
03/27/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651  
Name of Operator: VERDAD RESOURCES LLC  
Address: 5950 CEDAR SPRINGS ROAD  
City: DALLAS State: TX Zip: 75235  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Michael Cugnetti</u>	<u>720-845-6901</u>	<u>mcugnetti@verdadresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696301521  
Inspection Date: 03/10/2020 FIR Submit Date: 03/10/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC Company Number: 10651  
Address: 5950 CEDAR SPRINGS ROAD  
City: DALLAS State: TX Zip: 75235

LOCATION - Location ID: 433368

Location Name: Nelson Ranches Number: 1-33-10-59 County: \_\_\_\_\_  
Qtrqr: SWSE Sec: 28 Twp: 10N Range: 59W Meridian: 6  
Latitude: 40.804320 Longitude: -103.981150

FACILITY - API Number: 05-123-00 Facility ID: 433368

Facility Name: Nelson Ranches Number: 1-33-10-59  
Qtrqr: SWSE Sec: 28 Twp: 10N Range: 59W Meridian: 6  
Latitude: 40.804320 Longitude: -103.981150

CORRECTIVE ACTIONS:

1 CA# 137080

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

Date: 03/25/2020

Response: CA COMPLETED Date of Completion: 03/24/2020

Operator Comment: stained soil removed and properly disposed of from areas around engines exhaust and near tanks.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed:

Title: Director of EHS&R

Date: 3/27/2020 11:28:09 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402354524	Engine exhaust CA photo documentation
402354525	Tanks stained soil CA photo documentation

Total Attach: 2 Files