

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 1 – Grant Tank Batter Sign



40.11282, -104.97943, 8221.8ft
03/25/2020 12:03:46

Photo 2 – Compressor with stained soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 3 – Buried concrete vessel behind compressor building



Photo 4 – Emissions Control Device



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 5 – View of oily waste stockpile and produced water vessel



Photo 6 – Oily Waste Stockpile



Inspection Photos
Location Name: Grant Tank Battery
Location ID: 446484



Photo 7 – Partially buried vessel



Photo 8 – Monitoring wells MW-3, MW-4 and TH-11



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources