

Banta Ridge 10-19-103
API: 05-103-10411
Inspection: 700400674



39.94795, -108.9959, 6060.9ft, 139°
03/26/2020 03:24:16 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Banta Ridge 10-19-103
API: 05-103-10411
Inspection: 700400674



39.94774, -108.99607, 6075.5ft, 126°
03/26/2020 03:24:47 PM

Banta Ridge 10-19-103
API: 05-103-10411
Inspection: 700400674




39.94765, -108.99557, 6065.9ft, 196°
03/26/2020 03:26:04 PM

Banta Ridge 10-19-103

API: 05-103-10411

Inspection: 700400674



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well head sign.