

Banta Ridge 5-9-1-103

API: 05-103-10156

Inspection: 700400676



39.97308, -108.96846, 5570.3ft, 358°

03/26/2020 03:51:35 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Banta Ridge 5-9-1-103
API: 05-103-10156
Inspection: 700400676



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well head.

Banta Ridge 5-9-1-103

API: 05-103-10156

Inspection: 700400676



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Meter building & separator.

Banta Ridge 5-9-1-103
API: 05-103-10156
Inspection: 700400676



39.97319, -108.96838, 5561.0ft, 167°
03/26/2020 03:52:22 PM