

Inspection Photos
Location Name: Peppler Fee Com 12-18
Location ID: 313060



Photo 1. Overview of location taken facing west.



Photo 2. 2 risers on left side of photo not LOTO or marked for abandonment.

