

Inspection Photos
Location Name: McCallum Unit 117
Location ID: 324688



Photo 1. Overview of location taken facing north.



Photo 2. No label on tank.

Inspection Photos
Location Name: McCallum Unit 117
Location ID: 324688



Photo 3. Stained soil at wellhead.



Photo 4. Close-up of stained soil at wellhead.