

Inspection Photos
Location Name: McCallum Unit 128
Location ID: 324700



Photo 1. Overview of location taken facing north.



Photo 2. Stained soil at wellhead.

