

Inspection Photos
Location Name: McCallum Unit 91
Location ID: 324656



Photo 1. Overview of location taken facing west.



Photo 2. Stained soil at wellhead.

Inspection Photos
Location Name: McCallum Unit 91
Location ID: 324656



Photo 3. Stained soil at wellhead.



Photo 4. Stained soil at wellhead.