

Inspection Photos
Location Name: McCallum Unit 2
Location ID: 324586



Photo 1. Overview of location taken facing southwest.



Photo 2. Stained soil at wellhead.

Inspection Photos
Location Name: McCallum Unit 2
Location ID: 324586



Photo 3. Stained soil at wellhead.



Photo 4. Stained soil at wellhead.