

Axis Exploration LLC, Murphy 24-17
005-07080

Inspection #688307474

3/26/2020

PA Inspection



COLORADO

**Oil & Gas Conservation
Commission**


Department of Natural Resources



Cement ~4' from
surface.



Tubing from Murphy well.



Murphy tank battery equipment.

Colorado Oil and Gas Conservation Commission
39.60903, -104.46629, 5767.7ft, 92°
03/26/2020 12:37:15 PM