

Inspection Photos

Spill/Release Name: Red Rocks Gathering System Premier 6"

Spill/Release ID: 474138

Inspection Date: March 25, 2020



Spill location looking northeast.



Hydrovacing to located the 6-inch pipeline and the scraped soils around the excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Spill/Release Name: Red Rocks Gathering System Premier 6"

Spill/Release ID: 474138

Inspection Date: March 25, 2020



Excavation of the 6-inch pipeline.



6-inch pipeline excavation, the fluids around the pipeline are from hydrovacing.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Spill/Release Name: Red Rocks Gathering System Premier 6"
Spill/Release ID: 474138
Inspection Date: March 25, 2020



View of the small draining with waddles looking south.



View of the small draining with waddles looking north.

