

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2020

Submitted Date:

03/30/2020

Document Number:

700700376**FIELD INSPECTION FORM**Loc ID 334643 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270931	WELL	PR	06/11/2004	GW	045-09805	SOURS 15-11A (L15W)	PR
270932	WELL	SI	12/01/2019	GW	045-09804	SOURS 15-11B (L15W)	SI
270940	WELL	PR	11/05/2012	GW	045-09803	SOURS 15-13A (L15W)	PR
271504	WELL	PR	09/01/2019	GW	045-09896	SOURS 15-14A (L15W)	PR
275900	WELL	PR	11/01/2012	GW	045-10396	ROSE 15-12A (L15W)	PR
275901	WELL	PR	08/23/2005	GW	045-10397	ROSE 15-11D (L15W)	PR
275902	WELL	PR	09/01/2011	GW	045-10398	ROSE 15-13D (L15W)	PR
275903	WELL	PR	08/30/2005	GW	045-10399	ROSE 15-15B (L15W)	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 3/30/20 at approximately 9:00 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus L15W, at Location # 334643 in Garfield Colorado.

While there, I observed normal production operations. All C/A(s) have been completed from previous inspection document # 694901132. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	shared containment with condensate tanks				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	All holes in liner have been repaired			
Corrective Action:			Date:	

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 270931	Type: WELL	API Number: 045-09805	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 270932	Type: WELL	API Number: 045-09804	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: shut in				
Corrective Action:		Date:		
Facility ID: 270940	Type: WELL	API Number: 045-09803	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 271504	Type: WELL	API Number: 045-09896	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 275900	Type: WELL	API Number: 045-10396	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 275901	Type: WELL	API Number: 045-10397	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 275902	Type: WELL	API Number: 045-10398	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 275903	Type: WELL	API Number: 045-10399	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		

Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
		Gravel				
Ditches		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700384	photos for L15W	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5110399