

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT /15-12H2 (D14OU)

Location ID: 334142



Photo #0868 from entrance to location



Photo #0872 500 gallon methanol tank missing operator's name.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT /15-12H2 (D14OU)

Location ID: 334142



**Photo #0869 Multiple place with unused equipment on location.**



**Photo #0870 Multiple place with unused equipment on location.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT /15-12H2 (D14OU)

Location ID: 334142



**Photo #0871 Oily fluid in Methanol tank containment.**