

Inspection Photos

Loc#416703

Operator: Ursa

Inspection Number: 692402015

Inspection Date: 3/17/20





Photo#1:
Overview of Location from entry.

March 17, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley Farms J Pad Loc#416703




Photo#2:
API#045-22340 showing open gap .

March 17, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:
Adjacent Well, where gap is filled in.

Inspection Photos: Ursa Valley Farms J Pad Loc#416703



Photo#4:
Unmarked, damaged Anchor.



Photo#5:
Weedy area of Interim area.

March 17, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley Farms J Pad Loc#416703