

Inspection Photos

Loc#436713

Operator: Ursa

Inspection Number: 692402016

Inspection Date: 3/17/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry and Well lineups.

March 17, 2020



Photo#2:
Boards not in position to allow means of Wildlife egress. & Subsidence developing

March 17, 2020

Photo#3:
Boards not in position to allow means of Wildlife egress.



Photo#4:
Weedy area of berms.



Photo#5:
Weedy area of berms.

March 17, 2020