

# *Inspection Photos*

*Loc#438312*

*Operator: Ursa*

*Inspection Number: 692402018*

*Inspection Date: 3/18/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry and Well lineup.

March 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa TompkinsL Pad Loc#438312



Photo#2:  
Weedy areas of berms and slopes

Photo#3:  
Weedy areas of berms and slopes

March 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa TompkinsL Pad Loc#438312





Photo#4:  
Soil migration off Cut Slope.



Photo#5:  
Erosion commencing on Cut Slope.


March 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa TompkinsL Pad Loc#438312





Photo#6:  
Soil migration off Cut Slope.



Photo#7:  
Subsidence at electrical riser..

March 18, 2020