

Inspection Photos

Loc#447695

Operator: Ursa

Inspection Number: 692402019

Inspection Date: 3/18/20




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry and Well lineup.



March 18, 2020



Photo#2:
Weedy perimeter area.



Photo#3:
Weedy perimeter area.

March 18, 2020



Photo#4:
Weeds have become Debris.

March 18, 2020



Photo#5:
Weedy area along site perimeter.



Photo#6:
Area of Vegetation concern.

March 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#7:
Area of Vegetation concern.

Inspection Photos: Ursa BMC B Pad Loc#447695



Photo#8:
Stormwater concerns along Access Road



Photo#9:
Stormwater concerns along Access Road.

March 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa BMC B Pad Loc#447695