

Dragon Trail Unit 1014

API: 05-103-05932

Inspection: 700400740



39.84031, -108.83991, 6954.2ft, 108°

03/30/2020 10:51:14 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Dragon Trail Unit 1014
API: 05-103-05932
Inspection: 700400740



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Tank & meter building.

Dragon Trail Unit 1014

API: 05-103-05932

Inspection: 700400740



39.84026, -108.83956, 6963.4ft, 137°

03/30/2020 10:52:01 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Sediment flowing unto location over berm.

Dragon Trail Unit 1014

API: 05-103-05932

Inspection: 700400740



39.84089, -108.83704, 6982.6ft, 83°
03/30/2020 10:55:35 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Stormwater channel in lease road.