

Inspection Photos

Location Name: VPR C NO. 76 CA DATE 4-30-20

API#: 05-071-07322

INSP. #: 695102449



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos

Location Name: VPR C NO. 76 CA DATE 4-30-20

API#: 05-071-07322

INSP. #: 695102449



PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT ACCORDING TO RULE 603.f.
CA DATE 4-30-20

PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT ACCORDING TO RULE 603.f.
CA DATE 4-30-20

Inspection Photos

Location Name: VPR C NO. 76 CA DATE 4-30-20

API#: 05-071-07322

INSP. #: 695102449



PHOTO 5: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE UNUSED EQUIPMENT ACCORDING TO RULE 603.f.
CA DATE 4-30-20



PHOTO 6: IMPACTED SOIL AROUND COMPRESSOR
APPEARS TO BE HYDRALIC OIL FROM COMPRESSOR.
Conduct maintenance on equipment, cleanup
stained material and review self inspection
processes. CA DATE 4-30-20