

**Inspection Photos**  
**Location Name: Maudlin Gulch Unit 18**  
**Location ID: 312873**



**Photo 1. Overview of location taken facing northeast.**



**Photo 2. Tubing stored at wellhead.**



**Inspection Photos**  
**Location Name: Maudlin Gulch Unit 18**  
**Location ID: 312873**



**Photo 3. Sediment moving down access road and on left hand side of road.**



**Photo 4. Sediment moving down access road.**





**Inspection Photos**  
**Location Name: Maudlin Gulch Unit 18**  
**Location ID: 312873**



**Photo 5. Sediment moving down and across access road into drainage.**



**Photo 6. Sediment moving across access road.**

