

Inspection Photos

3/30/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 314813

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314813



Photo 1: Photo taken from the wellhead, facing east. Inspection #696201101 required Operator to comply with Rule 907.e by 4/1/2020. Photo shows stained soils remain evident along areas adjacent to the wellhead.



Photo 2: Photo of containment cellar at the wellhead. . Inspection #696201101 required Operator to remove fluids/chemicals within containment. Photo shows fluids/chemicals have not been removed per corrective actions.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314813




Photo 3: See comments under photo 2.



Photo 4: Photo taken from the wellhead. Inspection #696201101 documented venting from an open valve on equipment attached to the bradenhead. Valve appears to have been closed and well is no longer venting.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314813



Photo 5: Photo taken from the northwest end of the Location, facing northwest. Photo shows oily rags on the Location. This is trash debris and requires removal.



Photo 6: Photo taken from the west end of the Location, facing west. Photo shows cable on the Location. This is trash debris and requires removal.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314813



Photo 7: Photo taken from the southeast end of the Location, facing south. Photo shows the utility pole appears to have been cut above the electric box. Cut portion of the utility pole, as well as cable wires and the utility anchor was not removed, is considered unused equipment and trash debris, and requires removal.



Photo 8: Continued from photo 7. Photo shows utility anchor and cable.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314813



Photo 9: Continued from photo 7. Photo shows cut utility pole and cable wire.

