

# Inspection Photos

3/30/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 314650

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314650



**Photo 1:** Photo of well marker.



**Photo 2:** Photo taken from areas northwest of the well, facing southeast. Photo shows areas where stained soils with a petroleum odor was observed; previous inspection required operator to remove stained soils, remediate as needed and revegetate. Corrective action has not been addressed.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314650



**Photo 3:** Photo taken from areas northwest of the well, facing southeast. See comments under photo 2.



**Photo 4:** Photo taken from areas north of the well, facing northwest.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314650



**Photo 5:** Photo of cable debris observed within area of the well.



**Photo 6:** Photo of cable debris observed within area of the well.