

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 1 – Wellhead



Photo 2 – Signage

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 3 – Location Overview

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 4 – Unmarked Risers and old Heater Treater shed.



Photo 5 – Unmarked Risers and old Heater Treater shed.

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 6 – SE Pit



Photo 7 – NE Pit; holes in lining

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 8 – West Pit; hole in lining and weeds



Photo 9 – Trash/Unused chemical container

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 10 – Trash/Unused chemical container



Photo 11 – Oily waste in 5 Gallon bucket at old Tank Berm

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 12 – Unmarked Risers



Photo 13 – Stained Soil

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 14 – Stained Soil



Photo 15 – Stained Soil, Unused Stands and Trash

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 16 – Unused Equipment



Photo 17 – Lease Road Erosion

Inspection Photos
Location Name: Dolan Ranches 13-27
Location ID: 317614



Photo 18 – Lease Road Erosion



Photo 19 – Lease Road Erosion