

# Inspection Photos

Location Name: AP 12-02V CA DATE 4-30-20

API#: 05-071-07407

INSP. #: 695102485



Colorado Oil & Gas Conservation Commission  
37.01411, -104.49208, 161°  
2020/03/31 14:38:58



GAS PROCESSING EQUIPMENT

LAT 37.102504  
LONG 104.943002

719-497-0446  
or 911

WDID 1912292  
PERMIT 74071

TIMBER CREEK  
APACHE CANYON 12-02V  
NW/NE 12-34S-68W  
NAD 83  
Lat. 37.102525  
Long. 104.954405

Colorado Oil & Gas Conservation Commission  
37.10275, -104.94284, 2442.0m, 201°  
2020/03/31 14:39:46

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

## Inspection Photos

Location Name: AP 12-02V CA DATE 4-30-20

API#: 05-071-07407

INSP. #: 695102485



**PHOTO 3: STANDING OIL IN COMPRESSOR SKID. COMPLY WITH GENERAL PERSIVIONS OF OIL AND GAS ACT PERTAINING TO WILDLIFE PROTECTION. CA DATE 4-30-20**

**PHOTO 4: AREA OF IMPACTED SOIL APPEARS TO BE OIL CONTAMINATION FROM COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.**

## Inspection Photos

Location Name: AP 12-02V CA DATE 4-30-20

API#: 05-071-07407

INSP. #: 695102485



Colorado Oil & Gas Conservation Commission  
37.10264, -104.94299, 2431.0m, 44°  
2020/03/31 14:41:11

**PHOTO 5: TWO UNMARKED UNUSED RISERS. COMPLY WITH  
NTO AND RULE 603.f. CA DATE 4-30-20.**