

# Inspection Photos

Location Name: AP 07-08 CA DATE 4-30-20

API#: 05-071-08300

INSP. #: 695102491



Colorado Oil & Gas Conservation Commission  
37.0994, -104.92435, 2423.0m, 69°  
2020/03/31 15:21:18



Colorado Oil & Gas Conservation Commission  
37.09935, -104.92402, 2399.0m, 60°  
2020/03/31 15:21:42

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

## Inspection Photos

Location Name: AP 07-08 CA DATE 4-30-20

API#: 05-071-08300

INSP. #: 695102491



**PHOTO 3: AREA OF IMPACTED SOIL ALL AROUND COMPRESSOR INSIDE SOUND WALLS. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.**

**PHOTO 4: STANDING OIL INSIDE OF COMPRESSOR SKID. COMPLY WITH GENERAL PERVERSIONS OF OIL AND GAS ACT & SB-181 PERTAINING TO WILDLIFE PROTECTION. CA DATE 4-30-20**