

Inspection Photos
Location Name: Ruhl 32H-B264 East/West TB
Location ID: 439042



Photo 1 TB signs



Photo 2 TB



Inspection Photos
Location Name: Ruhl 32H-B264 East/West TB
Location ID: 439042




Photo 3 ECDs



Photo 4 Compressor

Inspection Photos
Location Name: Ruhl 32H-B264 East/West TB
Location ID: 439042



Photo 5 Vertical Separator




Photo 6 Horizontal heated separators

Inspection Photos
Location Name: Ruhl 32H-B264 East/West TB
Location ID: 439042



Colorado Oil & Gas Conservation Commission
 26034 Co Rd 16, Keenesburg, CO 80643, USA
 40.10027, -104.56789, 4945.7ft, 274°
 03/31/2020 13:41:24



Colorado Oil & Gas Conservation Commission
 25931 Co Rd 16, Keenesburg, CO 80643, USA
 40.10029, -104.56796, 4945.0ft, 160°
 03/31/2020 13:41:37

Photo 7 Gas meter run

Photo 8 Card inside meter house