

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/31/2020

Submitted Date:

03/31/2020

Document Number:

689704471

FIELD INSPECTION FORM

Loc ID 335806	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 34 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280076	WELL	PR	02/01/2014	GW	045-11175	N. PARACHUTE EF08B P27 595	PR
421110	WELL	PR	05/23/2012	GW	045-20282	N. Parachute EF08D-34 P27595	PR
421111	WELL	PR	10/17/2012	GW	045-20283	N. Parachute EF14F-27 P27595	PR
421112	WELL	PR	10/15/2012	GW	045-20284	N. Parachute EF01E-34 P27595	PR
421113	WELL	PR	11/14/2012	GW	045-20285	N. Parachute EF16F-27 P27595	PR
421114	WELL	PR	01/08/2013	GW	045-20286	N. Parachute EF11F-27 P27595	PR
421115	WELL	PR	05/23/2012	GW	045-20287	N. Parachute EF08B-34 P27595	PR
421116	WELL	PR	06/17/2011	GW	045-20288	N. Parachute EF08A-34 P27595	PR
421117	WELL	PR	07/12/2013	GW	045-20289	N. Parachute EF01C-34 P27595	PR
421118	WELL	PR	07/12/2013	GW	045-20290	N. Parachute EF11D-27 P27595	PR
421119	WELL	PR	01/08/2013	GW	045-20291	N. Parachute EF14A-27 P27595	PR
421120	WELL	PR	01/08/2013	GW	045-20292	N. Parachute EF09F-27 P27 59	PR
421121	WELL	PR	02/14/2013	GW	045-20293	N. Parachute EF14B-27 P27595	PR
421122	WELL	PR	02/14/2013	GW	045-20294	N. Parachute EF16C-27 P27595	PR

421123	WELL	PR	12/14/2012	GW	045-20295	N. Parachute EF16D-27 P27595	PR
421124	WELL	PR	12/01/2012	GW	045-20296	N. Parachute EF16E-27 P27595	PR
421125	WELL	PR	06/16/2012	GW	045-20297	N. Parachute EF01F-34 P27595	PR
421126	WELL	PR	06/08/2013	GW	045-20298	N. Parachute EF01A-34 P27595	PR
421127	WELL	PR	08/01/2014	GW	045-20299	N. Parachute EF09E-27 P27595	PR
421128	WELL	PR	01/08/2013	GW	045-20300	N. Parachute EF16A-27 P27595	PR
421129	WELL	PR	05/28/2013	GW	045-20301	N. Parachute EF11E-27 P27595	PR
421145	WELL	PR	04/01/2014	GW	045-20315	N. Parachute EF08E-34 P27595	PR
421147	WELL	PR	10/17/2012	GW	045-20317	N. Parachute EF14E-27 P27595	PR
421148	WELL	PR	11/12/2012	GW	045-20318	N. Parachute EF08F-34 P27595	PR
421149	WELL	PR	02/14/2013	GW	045-20319	N. Parachute EF14D-27 P27595	PR
421150	WELL	PR	12/12/2012	GW	045-20320	N. Parachute EF16B-27 P27595	PR
421152	WELL	PR	07/12/2013	GW	045-20322	N. Parachute EF01B-34 P27595	PR
421153	WELL	PR	07/12/2013	GW	045-20323	N. Parachute EF09D-27 P27595	PR
421154	WELL	PR	10/15/2012	GW	045-20324	N. Parachute EF01D-34 P27595	PR
422723	WELL	AL	05/01/2018	LO	045-20613	N. Parachute EF WDW16B P27 595	AL

General Comment:Follow Up Field inspection

On 03/31/2020 at approximately 1220 hours, I, Inspector Mike Longworth, conducted a follow up field inspection at CAERUS PICEANCE LLC N. Parachute EF P27 595 Location # 335806 in Garfield County, Colorado
All corrective actions have been addressed from 01/03/2019 Inspection 689702342.

Location

Lease Road:			
Type	Main		
comment:	Accessed fro CR215		
Corrective ActionL		Date:	
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911 Access road CR 215	
Corrective Action:		Date:

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type:	#		
Comment:			
Corrective Action:			Date:
Type:	#		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	280076	Type:	WELL	API Number:	045-11175	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	421110	Type:	WELL	API Number:	045-20282	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	421111	Type:	WELL	API Number:	045-20283	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	421112	Type:	WELL	API Number:	045-20284	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	421113	Type:	WELL	API Number:	045-20285	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	421114	Type:	WELL	API Number:	045-20286	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	421115	Type:	WELL	API Number:	045-20287	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	421116	Type:	WELL	API Number:	045-20288	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID:	421117	Type:	WELL	API Number:	045-20289	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421118	Type:	WELL	API Number:	045-20290	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421119	Type:	WELL	API Number:	045-20291	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421120	Type:	WELL	API Number:	045-20292	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421121	Type:	WELL	API Number:	045-20293	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421122	Type:	WELL	API Number:	045-20294	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421123	Type:	WELL	API Number:	045-20295	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421124	Type:	WELL	API Number:	045-20296	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	421125	Type:	WELL	API Number:	045-20297	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421126	Type:	WELL	API Number:	045-20298	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421127	Type:	WELL	API Number:	045-20299	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421128	Type:	WELL	API Number:	045-20300	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421129	Type:	WELL	API Number:	045-20301	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421145	Type:	WELL	API Number:	045-20315	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421147	Type:	WELL	API Number:	045-20317	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421148	Type:	WELL	API Number:	045-20318	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 421149	Type: WELL	API Number: 045-20319	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 421150	Type: WELL	API Number: 045-20320	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 421152	Type: WELL	API Number: 045-20322	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 421153	Type: WELL	API Number: 045-20323	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 421154	Type: WELL	API Number: 045-20324	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 422723	Type: WELL	API Number: 045-20613	Status: AL	Insp. Status: AL
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Gravel	Pass			
		Compaction	Pass			
				Material Handling And Spill Prevention	Pass	
		Culverts	Pass			
Gravel	Pass					
Check Dams	Pass					
		Ditches	Pass			
Ditches	Pass					
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704472	Inspection 689704471 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5112045