

Final Reclamation Inspection

March 18, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 309936

Inspection Document #: 697501255

Weld County, CO

SWSW Section 8 T5N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PAULINE PJ #5
Location ID: 309936



Photo 1. Photo taken from the offsite tank battery location, facing South. Photo illustrates a pipeline disturbance from Tallgrass Energy.

Inspection Photos
Location Name: PAULINE PJ #5
Location ID: 309936



Photo 2. Photo taken from the offsite tank battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: PAULINE PJ #5
Location ID: 309936



Photo 3. Photo taken from the well location, facing West. Photo illustrates the well location is reflective of reference area vegetative levels.

Inspection Photos
Location Name: PAULINE PJ #5
Location ID: 309936



Photo 4. Photo taken from the well location, facing Southwest. Photo illustrates the well location access road is reflective of reference area vegetative levels.