

Final Reclamation Inspection

March 18, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 322835

Inspection Document #: 697501257

Weld County, CO

NWSW Section 8 T5N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PAULINE #2
Location ID: 322835



Photo 1. Photo taken from the offsite tank battery location, facing South. Photo illustrates a pipeline disturbance from Tallgrass Energy.

Inspection Photos
Location Name: PAULINE #2
Location ID: 322835



Photo 2. Photo taken from the offsite tank battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: PAULINE #2
Location ID: 322835



Photo 3. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: PAULINE #2
Location ID: 322835



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.