

Inspection Photos
Location Name: Gracie LD22-750
Location ID: 441911



Photo 1 – Gracie Wells



Photo 2 – Tank Battery

Inspection Photos
Location Name: Gracie LD22-750
Location ID: 441911



Photo 3 – Unused Stairs South of Flare



Photo 4 – Unused Stairs at Gas Meters

Inspection Photos
Location Name: Gracie LD22-750
Location ID: 441911



Photo 5 – Vault North of Compressors is missing Content and Capacity