

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2020

Submitted Date:

04/01/2020

Document Number:

695102501

**FIELD INSPECTION FORM**

Loc ID 308004 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10351  
Name of Operator: WAPITI OPERATING LLC  
Address: 1310 W SAM HOUSTON PKWY N  
City: HOUSTON State: TX Zip: 77043

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Berry, Matthew	575-445-6785/505-652-8275	mberry@wapitienergy.com	Production Foreman
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	EHS Specialist
Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com	Production superintendent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260125	WELL	PR	01/08/2002	GW	071-07386	VPR C 84	PR

**General Comment:**

**Inspected Facilities**

Facility ID: 260125 Type: WELL API Number: 071-07386 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOWUP TO INSPECTION DOC#695102301. BASED ON PHOTOS SUBMITTED BY OPERATOR ON FIRR DOC#402352916 CA IS APPROVED.	beardsit	04/01/2020