

Inspection Photos
Operator: BP America
API#: 067-06681
Date: 3/31/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass and smooth brome.



Photo 3. View of reference area vegetation within an open grass field, largely comprised with smooth brome.