

Inspection Photos
Operator: BP America
API#: 067-06140
Date: 3/31/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward.



Photo 3. View of reference area vegetation within an open grass field, largely comprised with smooth brome.