

Final Reclamation Inspection

March 31, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 336435

Inspection Document #: 697501271

Weld County, CO

SENE Section 18 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KUGEL #42-18
Location ID: 336435



Photo 1. Photo taken from the Kugel 42-18 well location, facing North. Photo illustrates Operator has failed to remove a riser per Rule 1004.a.

Inspection Photos
Location Name: KUGEL #42-18
Location ID: 336435



Photo 2. Photo taken from the Miller 12-17 well location, facing North. Photo illustrates Operator has removed all equipment for this well.

Inspection Photos
Location Name: KUGEL #42-18
Location ID: 336435



Photo 3. Photo taken from the Kugel and Miller well location, facing South. Operator shall comply with reclamation rules to perform final reclamation by the required date.

Inspection Photos
Location Name: KUGEL #42-18
Location ID: 336435



Photo 4. Photo taken from the Kugel and Miller well location access road, facing South. See comments under Photo 3.

Inspection Photos
Location Name: KUGEL #42-18
Location ID: 336435



Photo 5. Photo taken from the associated offsite tank battery location, facing North. Photo illustrates Operator has removed all equipment and has performed final reclamation activities with the evidence of drill rows and straw crimped mulch.

Inspection Photos
Location Name: KUGEL #42-18
Location ID: 336435



Photo 6. Photo taken from the associated offsite tank battery location, facing South. See comments under Photo 5.