

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



Colorado Oil And Gas Conservation Commission  
40.26952, -105.02167, 1528.0m  
04/01/2020 9:14:34 AM

**Lease road sign**



Colorado Oil And Gas Conservation Commission  
40.26936, -105.02275, 1526.0m  
04/01/2020 9:15:49 AM

**Location**

Inspection Photos  
Location Name: Markham Pad  
Location ID: 446104



Wellheads



Lease road sign and trash

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Lease road damage**



**Lease road damage**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Lease road damage**



**Lease road damage**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Lease road damage**



**Unused equipment**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Location damage**



**Master valve leak**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Master valve leak**




**Master valve leak**

Inspection Photos  
Location Name: Markham Pad  
Location ID: 446104



Master valve leak



Master valve leak

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**ECD unit and crude oil**



**ECD unit, crude oil and flame arrester**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**ECD unit and crude oil**



**ECD unit and crude oil**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**ECD unit and crude oil**



**ECD unit and crude oil**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



Colorado Oil And Gas Conservation Commission  
40.26864, -105.02368, 1526.0m  
04/01/2020 9:31:25 AM

**ECD unit and crude oil**



Colorado Oil And Gas Conservation Commission  
40.26864, -105.02371, 1526.0m  
04/01/2020 9:32:03 AM

**Broken glass from fire extinguisher rack**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Fire extinguisher rack**



**Burned ECD**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Burned ECD**



**Burned ECD**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Burned ECD**



**Burned ECD**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Lube oil storage**



**Chemical storage**

Inspection Photos  
Location Name: Markham Pad  
Location ID: 446104



Colorado Oil And Gas Conservation Commission  
40.26922, -105.02357, 1506.0m  
04/01/2020 9:43:18 AM

Chemical storage



Colorado Oil And Gas Conservation Commission  
40.26915, -105.02358, 1512.0m  
04/01/2020 9:43:32 AM

Chemical storage

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



Colorado Oil And Gas Conservation Commission  
40.26915, -105.02352, 1519.0m  
04/01/2020 9:42:13 AM

**Chemical storage and trash**



Colorado Oil And Gas Conservation Commission  
40.26915, -105.02356, 1518.0m  
04/01/2020 9:42:30 AM

**Chemical storage and trash**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Chemical storage**



**Chemical storage**

Inspection Photos  
 Location Name: Markham Pad  
 Location ID: 446104



Produced water tank placards



Produced water tank placards

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**VRT placards**



**VRT placards**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Trash**



**Trash**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



Colorado Oil And Gas Conservation Commission  
40.26855, -105.02407, 1519.0m  
04/01/2020 9:34:58 AM

**Trash**



Colorado Oil And Gas Conservation Commission  
40.2685, -105.02337, 1521.0m  
04/01/2020 9:58:30 AM

**Trash**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Trash and stained soil**



**Trash**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



Colorado Oil And Gas Conservation Commission  
40.26915, -105.02371, 1525.0m  
04/01/2020 9:40:52 AM

**Trash and stained soil**



Colorado Oil And Gas Conservation Commission  
40.26932, -105.02391, 1507.0m  
04/01/2020 9:45:54 AM

**Trash**

**Inspection Photos**  
**Location Name: Markham Pad**  
**Location ID: 446104**



**Trash**




**Stained soil**

Inspection Photos  
 Location Name: Markham Pad  
 Location ID: 446104



Colorado Oil And Gas Conservation Commission  
 40.26868, -105.02375, 1522.0m  
 04/01/2020 9:32:21 AM

Stained soil



Colorado Oil And Gas Conservation Commission  
 40.26497, -105.01032, 1573.0m  
 04/01/2020 9:55:44 AM

Noble meter calibration card