

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/28/2020

Submitted Date:

04/01/2020

Document Number:

688307490**FIELD INSPECTION FORM**
 Loc ID 320787 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10646Name of Operator: AXIS EXPLORATION LLCAddress: 370 17TH ST SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Dunning, Michael	303 396-6040	mdunning@extractionog.com	
Extraction Oil & Gas	720-370-5540	COGCCInspections@extracti onog.com	
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204921	WELL	SI	05/01/2018	GW	005-07006	BENNETT A-4	SI

**General Comment:**MIT Inspection, passed

**Location**Overall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 204921 Type: WELL API Number: 005-07006 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment:

Anytime Testing  
 0 psi Casing, Tubing and Bradenhead  
 0 min 507 psi  
 5 min 506 psi  
 10 min 505 psi  
 15 min 505 psi  
 0 psi Casing, Tubing and Bradenhead  
 Operator completed Form 21 on the computer and will submit within 10 days

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Workover**Comment:

Ensign Rig 351

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307606	Axis Exploration Bennett A-4	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5113034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5113034</a>