

WRD Unit 28-22
API: 05-103-10145
Inspection: 700400816



40.11481, -108.17247, 5848.9ft, 114°
04/01/2020 03:44:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

WRD Unit 28-22
API: 05-103-10145
Inspection: 700400816



40.11475, -108.17231, 5854 5ft, 115°
04/01/2020 03:44:49 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well head, meter building, and tanks.

WRD Unit 28-22
API: 05-103-10145
Inspection: 700400816



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator.

WRD Unit 28-22
API: 05-103-10145
Inspection: 700400816



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Meter building.

WRD Unit 28-22
API: 05-103-10145
Inspection: 700400816

