



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Cole Nichols (colen@horizonenvservices.com)  
Submission Date: Mar 26, 2020 1:07:51 PM MDT  
Server Receive Date: Mar 26, 2020 1:11:04 PM MDT  
Reference Number: 20200326-18137670159  
Location: 557 Airpark Dr, Durango, CO 81303, USA  
Mar 26, 2020 1:10:13 PM MDT [ [View Map](#) ]

## Information

Name colen@horizonenvservices.com  
Date Mar 25, 2020  
Well Name DUSTIN GAS UNIT 09-01 1  
API Number 50670665100  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2


treated noxious weeds on entrance road

Photo of third corrective action completed



Completed work description of corrective action 3  
 Photo of fourth corrective action completed

musk thistle rosettes treated



Completed work description  
 Completed work description of corrective action 4  
 Additional photos

cheatgrass along road treated  
 treated noxious weeds



Additional photos



Additional photos



Additional photos



Additional photos



Completed work description

this site will be revisited again during selective application

Summary of all work completed

treated 6/27/17, 6/13/18, 5/7/19