



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Cole Nichols (colen@horizonenvservices.com)  
Submission Date: Apr 1, 2020 9:35:05 AM MDT  
Server Receive Date: Apr 1, 2020 9:38:06 AM MDT  
Reference Number: 20200401-18138127276  
Location: 557 Airpark Dr, Durango, CO 81303, USA  
Apr 1, 2020 9:38:01 AM MDT [ [View Map](#) ]

## Information

Name colen@horizonenvservices.com  
Date Mar 30, 2020  
Well Name WIRT GAS UNIT D DK 1  
API Number 50670511500  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

removed Russian thistle

Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed

removed Russian thistle



Completed work description  
Completed work description of corrective action 4  
Additional photos

removed Russian thistle  
removed Russian thistle from site



Completed work description  
Summary of all work completed

removed Russian thistle from site  
previous treatment dates 7/19/16, 7/21/17, 6/11/18  
and 9/3/19