



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Cole Nichols (colen@horizonenvservices.com) |
| Submission Date: | Apr 1, 2020 11:29:03 AM MDT |
| Server Receive Date: | Apr 1, 2020 11:32:06 AM MDT |
| Reference Number: | 20200401-18138138561 |
| Location: | 557 Airpark Dr, Durango, CO 81303, USA Apr 1, 2020 11:28:20 AM MDT [View Map] |

Information

| | |
|-----------------|--------------------------------|
| Name | colen@horizonenvservices.com |
| Date | Mar 31, 2020 |
| Well Name | FEDERAL LAND BANK GAS UNIT B 2 |
| API Number | 50670837700 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Other |

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated Russian knapweed

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

treated musk thistle



Completed work description
 Completed work description of corrective action 4
 Additional photos

treated Russian knapweed on south side of location
 treated noxious weeds



Completed work description
 Summary of all work completed

treated noxious weeds- will continue to monitor this location
 previous treatment dates 6/14/16, 6/29/17, 6/21/18, 5/13/19