



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 2, 2020 2:10:37 PM MDT
Server Receive Date:	Apr 2, 2020 2:10:45 PM MDT
Reference Number:	20200402-18138268278
Location:	3261 Co Rd 514, Ignacio, CO 81137, USA Apr 2, 2020 2:09:30 PM MDT [View Map]

Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 1, 2020
Well Name	PEARSON, HARRY GAS UNIT A 1
Location Name (Other)	Pearson Harry Gas unit A3
API Number	50670684600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Fencing Clean Up Land Owner Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up landowners trash / power poles

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



Built fence between location and landowners

Completed work description of corrective action 3

Photo of fourth corrective action completed



Had landowners move farm equipment off of location

Completed work description of corrective action 4

Summary of all work completed

Picked up trash.

Built fence between landowners and well location, clean up landowners trash/ power poles and had landowners move farm equipment off of location.