



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Apr 2, 2020 2:14:55 PM MDT
Server Receive Date:	Apr 2, 2020 2:18:05 PM MDT
Reference Number:	20200402-18138267445
Location:	557 Airpark Dr, Durango, CO 81303, USA Apr 2, 2020 2:14:04 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Apr 1, 2020
Well Name	GALLEGOS, BONIFACIO GAS UNIT A 2
Location Name (Other)	Bonifacio Gallegos A3
API Number	50670905900
Location API (Other)	0506709930
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed



treated musk thistle rosettes

Completed work description of corrective action 3

Photo of fourth corrective action completed



treated musk thistle rosettes

Completed work description

Completed work description of corrective action 4

Additional photos



treated musk thistle rosettes

treated noxious weeds in reclamation area and on entrance road.

Additional photos



Additional photos



Completed work description

Summary of all work completed

treated noxious weeds in reclamation area and on the entrance road

previous treatment dates 6/24/16, 7/7/17, 6/23/18 and 6/18/19