



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Apr 2, 2020 3:09:21 PM MDT
Server Receive Date:	Apr 2, 2020 3:12:25 PM MDT
Reference Number:	20200402-18138274573
Location:	557 Airpark Dr, Durango, CO 81303, USA Apr 2, 2020 3:09:20 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Apr 1, 2020
Well Name	JACQUEZ, THOMAS GAS UNIT E 1
API Number	50670759000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

removed old erosion logs from pad

Photo of second corrective action completed



Completed work description of corrective action 2

treated Russian knapweed on pipeline right of way

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed



Completed work description
Completed work description of corrective action 4
Completed work description
Summary of all work completed

treated Russian knapweed

treated Russian knapweed
treated Russian knapweed and removed erosion log
debris
removed erosion logs and treated noxious weeds
previous treatment dates 6/29/16, 7/26/17, 7/24/18
and 5/14/19