

Inspection Photos

Loc#335063

Operator: Terra

Inspection #: 692402039

Inspection Date: 3/25/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to Southeast and Interim Reclamation area.

March 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed Loc#335063



Photo#2:
Close ups of Pad Surface.

March 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:
Close ups of Pad Surface.

Inspection Photos: Terra Fed Loc#335063



Photo#4
Fence in disrepair.

March 25, 2020



Photo#5:
Vehicle short cut.

Inspection Photos: Terra Fed Loc#335063



Photo#6:
BMPs needing maintenance.

March 25, 2020



Photo#7:
BMPs needing maintenance.