

Final Reclamation Inspection

March 31, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 317588

Inspection Document #: 697501279

Weld County, CO

NENE Section 18 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KUGEL # 1
Location ID: 317588




Photo 1. Photo taken from the well location, facing Southeast. Photo illustrates the Operator has removed all equipment and has performed final reclamation activities with the evidence of straw and hydromulch. Photo also illustrates the flowline removal area and the offsite tank battery.



Photo 2. Photo taken from the well location, facing Southeast. Photo illustrates the flowline removal area.

Inspection Photos
Location Name: KUGEL # 1
Location ID: 317588



Photo 3. Photo taken from the associated offsite tank battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: KUGEL # 1
Location ID: 317588



Photo 4. Photo taken from the associated offsite tank battery location, facing South.
See comments under Photo 1.