

Inspection Photos
Location Name: Iles Dome Unit 26
Location ID: 312753



Photo 1. Overview of location taken facing north.



Inspection Photos
Location Name: Iles Dome Unit 26
Location ID: 312753



Photo 2. Erosion on pipeline crossing.



Photo 3. Erosion on pipeline crossing.