

# *Inspection Photos*

*Loc#335569*

*Operator: Terra*

*Inspection #: 692402053*

*Inspection Date: 4/3/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to North.

April 4, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335569





Photo#2:  
Overview of Location to South

April 4, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335569





Photo#3:  
Wattles installed at perimeter.



Photo#4:  
Wattles at presumed Topsoil Pile.

April 4, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335569





Photo#5:  
Ditch/check dams along West cut slope.

April 4, 2020



Photo#6:  
Ditch/check dams along West cut slope.



Photo#7:

Cut slope of concern along West side of site. Insert is Anchor marked with no bright color.

April 4, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335569





Photo#8:  
View of pit excavation from East Cut slope,  
where material is being layered.



Photo#9:  
West Pit wall, accumulation of stained soil.

April 4, 2020





Photo#10:  
View along West Pit wall and stained area.



Photo#11:  
Close up of stained soil on pit wall.

April 4, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Fed RWF Loc#335569