

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2020

Submitted Date:

04/06/2020

Document Number:

699101418

FIELD INSPECTION FORM

Loc ID: 450479 Inspector Name: Burns, Adam On-Site Inspection: 2A Doc Num: _____

Operator Information:
 OGCC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 1001 NOBLE ENERGY WAY
 City: HOUSTON State: TX Zip: 77070

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 9 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448090	TANK BATTERY	AC	10/19/2016		-	Hanscome C #21-19 448090	AC

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input type="text" value="Adequate"/>
Corrective Action:	<input type="text"/> Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Barbwire around Meter Run		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.303030,-104.557940
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

Flaring:

Type	
------	--

Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 448090 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 4/6/20 at approximately 1108 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Hanscome C21-19 & Chenoweth 1 Tank Battery of Noble Energy at Facility ID: 448090 in Weld County, Colorado. While there, I observed a Tank Battery No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report. Continuing education inspections</p>	burnsa	04/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699101419	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116298